BRITPART

New Product Information

January 2019

The quality parts for Land Rovers



Defender - from 1983 onwards & Series 2 & 3

These stainless steel door threshers will freshen up the inside of your Land Rover as this is an area is which can get very scruffy. All of the existing holes on the sills line up with these doors threshers so they are a quick, easy bolt on project. The door threshes are made from stainless steel 304 grade bright annealed 1.5mm thick and are laser cut and CNC pressed. Stainless steel fixings are supplied. **Note** - If your door seal is fitted to your sill rail, you may need to modify the sill rail.

Stainless Steel Brake Shield Bracket



DA4789

Defender Discovery 1

Range Rover Classic

Stainless steel rear brake shield bracket. Single. Manufactured from stainless steel 316 grade, 3mm thick and laser cut. Equivalent to LR017513 & FTC3299.

Stainless Steel Chassis Shock Mount Washers



DA4788

Defender / Discovery 1 Range Rover Classic

Set of 4. Stainless steel top of rear chassis shock mount washers. CNC machined from 316 stainless steel. Equivalent to RYF500210 & RYF500220.



DA4790

Front door threshers

For vehicles without sill seat belt mounts **DA4791**

Front door threshers

For vehicles with sill seat belt mounts

DA4792

2nd row door threshers

DA4793

Front & 2nd row door threshers
For vehicles without sill seat belt mounts

DA4794

Front & 2nd row door threshers
For vehicles with sill seat belt mounts

PRICE FROM

Stainless Steel Rear Crossmember



DA4795

Defender / Series 2 & 3

Stainless steel rear crossmember fixing kit. To bolt rear tub to rear body mounting to chassis. These are like for like on Defender TDCi rear cross member but in stainless steel A4-80.

4 x M8 A4-80 x 20mm Hex Head Bolts 10 x M8 A4-70 x 30mm Pan Head Bolts 4 x M8 A4 Spring Washers 14 x M8 A4 Flat Washers 1 x T40 Bit

uksales@britpart.co.uk

www.britpart.com



Britpart, The Grove, Craven Arms, Shropshire, SY7 8DA, UK

Prices include VAT.

Part numbers are used for identification purposes only and do not imply or indicate the identity of the manufacturer. E&OE.

Available from